

## Manhattan Plaza HDR-S v1.5.3 Release Notes - 06/06/2015

### Change Log

#### v1.5.3 (from v1.4.0)

- Fixed an intermittent issue with some UHD TVs (e.g. Sony Bravia KD-49X8505B) causing the receiver to stop responding.
- Updated the 'Signal Check' during Installation to scan for the Freesat Home Transponder in case its location changes in the future. Please see the below notes.

### Notes on the updated Signal Check



1. During the 'Signal Check' step the receiver scans for Freesat's Home Transponder and displays '**Scanning for Freesat; please wait...**' This can take up to 2 minutes to complete.

**Please note** that whilst scanning signal levels will not be displayed for LNB IN 2.



2. After successfully finding the Home Transponder and verifying the connected signals the message '**The signal check was successful**' is displayed and the '**Next**' button is highlighted.

Press '**OK**' on the remote control to proceed to the next step.