

Manhattan Plaza HD-T2 v1.35 Release Notes - 30/05/18

Please note that due to the changes in this release, after upgrade, the receiver will automatically reset to factory default and all user settings such as below will be lost:

- Favourites
- Reminders
- Deleted channels
- Settings

After reset, the installation process will start. Please follow the on-screen prompts to install and if you need assistance, refer to the “**Tuning In**” section on page 12 of the User Guide.

Change Log

v1.35 (from v1.34)

Recent changes in transmission re; Com 7/8

- Due to recent changes in transmission the EPG data carried by Com7/8 channels have increased 5 folds which slowed down the general operations when using the Guide whilst watching a channel from Com7/8. This has been fixed.